



PLYMOUTH SERVICE INFORMATION BULLETIN

Group

Fuel

Number

14-7

Date

March 2, 1960

1960 Model

Of interest to: SERVICE MGR.

SHOP FOREMAN

PARTS MGR.

MECHANICS

SUBJECT: BULLETIN CORRECTION

The part number mentioned at the bottom of page 3 of Plymouth Service Information Bulletin No. 14-5, dated January 13, 1960 is incorrect.

Carburetor linkage for the Sonoramic engine is serviced by components, not by a single part number as indicated.

The components are:

2129569 - Link - 2 per car

2128757 - Rod - 2 per car

The numbers are MoPar stock class code "P".

We suggest that copies of your Bulletin be corrected accordingly.

George J. Cutler
Director of Service
PLYMOUTH-DE SOTO-VALIANT DIVISION

P-985-C